

Parts needed to mount the 45-16 extrusion



Mounting bracket (A)



Extrusion (B)



LED strip (C)



Cover (D)



End Cap (E)


Tools needed for mounting:

- drill
- screwdriver
- screws


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at

- 1.** Feed the power cable. Attach the mounting bracket (A) to the mounting surface with screws.



- 2.** Mount the LED strip (C) in the extrusion (B) and insert the cover (D).



- 3.** Connect power to the LED strip and mount the extrusion in the mounting bracket. Insert the end cap.

